



Eurofins Environment Testing Australia Pty Ltd

ABN: 50 005 085 521

Melbourne
6 Monterey Road
Dandenong South
VIC 3175
+61 3 8564 5000
NATA# 1261
Site# 1254

Geelong
19/8 Lewalan Street
Grovedale
VIC 3216
+61 3 8564 5000
NATA# 1261
Site# 25403

Sydney
179 Magowar Road
Girraween
NSW 2145
+61 2 9900 8400
NATA# 1261
Site# 18217

Canberra
Unit 1,2 Dacre Street
Mitchell
ACT 2911
+61 2 6113 8091
NATA# 1261
Site# 25466

Brisbane
1/21 Smallwood Place
Murarrie
QLD 4172
+61 7 3902 4600
NATA# 1261
Site# 20794 & 2780

Newcastle
1/2 Frost Drive
Mayfield West
NSW 2304
+61 2 4968 8448
NATA# 1261
Site# 25079

Eurofins ARL Pty Ltd

ABN: 91 05 0159 898

Perth
46-48 Banksia Road
Welshpool
WA 6106
+61 8 6253 4444
NATA# 2377
Site# 2370 & 2554

web: www.eurofins.com.au

email: EnviroSales@eurofinsanz.com

Company Name: Australian Native Landscapes NSW
Address: 1 Pindimar Road
Tea Gardens
NSW 2324

Project Name:
Project ID: WESTON ANL

Order No.:
Report #: 1268587
Phone: 0498 655 499
Fax:

Received: Sep 16, 2025 10:25 AM
Due: Sep 23, 2025
Priority: 5 Day
Contact Name: Glenn Graves

Eurofins Analytical Services Manager : Andrew Black

Sample Detail						Ammonia (as N)	Conductivity (at 25 °C)	Oil & Grease (HEM)	pH (at 25 °C)	Total Suspended Solids Dried at 103°C to 105°C
Melbourne Laboratory - NATA # 1261 Site # 1254								X		
Sydney Laboratory - NATA # 1261 Site # 18217						X				
Mayfield West Laboratory - NATA # 1261 Site # 25079							X		X	X
External Laboratory										
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID					
1	Point 1 Outflow	Sep 16, 2025		Water	N25-Se0047054	x	x	x	x	x
2	Point 2 Upstream	Sep 16, 2025		Water	N25-Se0047055	x	x	x	x	x
Test Counts						2	2	2	2	2

Australian Native Landscapes NSW
1 Pindimar Road
Tea Gardens
NSW 2324



NATA Accredited
Accreditation Number 1261
Site Number 25079

Accredited for compliance with ISO/IEC 17025 – Testing
 NATA is a signatory to the ILAC Mutual Recognition
 Arrangement for the mutual recognition of the
 equivalence of testing, medical testing, calibration,
 inspection, proficiency testing scheme providers and
 reference materials producers reports and certificates.

Attention: **Glenn Graves**

Report **1268587-W**
 Project name
 Project ID **WESTON ANL**
 Received Date **Sep 16, 2025**

Client Sample ID			Point 1 Outflow	Point 2 Upstream
Sample Matrix			Water	Water
Eurofins Sample No.			N25- Se0047054	N25- Se0047055
Date Sampled			Sep 16, 2025	Sep 16, 2025
Test/Reference	LOR	Unit		
Ammonia (as N)	0.01	mg/L	0.02	0.02
Conductivity (at 25 °C)	10	uS/cm	860	860
Oil & Grease (HEM)	10	mg/L	< 10	< 10
pH (at 25 °C)	0.1	pH Units	7.1	7.7
Total Suspended Solids Dried at 103°C to 105°C	5	mg/L	< 5	11

Sample History

Where samples are submitted/analysed over several days, the last date of extraction is reported.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Ammonia (as N) - Method: LTM-INO-4200 Ammonia by Discrete Analyser	Sydney	Sep 17, 2025	28 Days
Conductivity (at 25 °C) - Method: LTM-INO-4030 Conductivity	Newcastle	Sep 16, 2025	28 Days
Oil & Grease (HEM) - Method: LTM-INO-4180 Oil and Grease	Melbourne	Sep 19, 2025	28 Days
pH (at 25 °C) - Method: LTM-GEN-7090 pH by ISE	Newcastle	Sep 16, 2025	6 Hours
Total Suspended Solids Dried at 103°C to 105°C - Method: LTM-INO-4070 Analysis of Suspended Solids in Water by Gravimetry	Newcastle	Sep 16, 2025	7 Days



web: www.eurofins.com.au
email: EnviroSales@eurofinsanz.com

Eurofins Environment Testing Australia Pty Ltd

ABN: 50 005 085 521

Melbourne
6 Monterey Road
Dandenong South
VIC 3175
+61 3 8564 5000
NATA# 1261
Site# 1254

Geelong
19/8 Lewalan Street
Grovedale
VIC 3216
+61 3 8564 5000
NATA# 1261
Site# 25403

Sydney
179 Magowar Road
Girraween
NSW 2145
+61 2 9900 8400
NATA# 1261
Site# 18217

Canberra
Unit 1,2 Dacre Street
Mitchell
ACT 2911
+61 2 6113 8091
NATA# 1261
Site# 25466

Brisbane
1/21 Smallwood Place
Murarrie
QLD 4172
+61 7 3902 4600
NATA# 1261
Site# 20794 & 2780

Newcastle
1/2 Frost Drive
Mayfield West
NSW 2304
+61 2 4968 8448
NATA# 1261
Site# 25079

Eurofins ARL Pty Ltd

ABN: 91 05 0159 898

Perth
46-48 Banksia Road
Welshpool
WA 6106
+61 8 6253 4444
NATA# 2377
Site# 2370 & 2554

Company Name: Australian Native Landscapes NSW
Address: 1 Pindimar Road
Tea Gardens
NSW 2324

Order No.:
Report #: 1268587
Phone: 0498 655 499
Fax:

Received: Sep 16, 2025 10:25 AM
Due: Sep 23, 2025
Priority: 5 Day
Contact Name: Glenn Graves

Project Name:
Project ID: WESTON ANL

Eurofins Analytical Services Manager : Andrew Black

Sample Detail						Ammonia (as N)	Conductivity (at 25 °C)	Oil & Grease (HEM)	pH (at 25 °C)	Total Suspended Solids Dried at 103°C to 105°C
Melbourne Laboratory - NATA # 1261 Site # 1254								X		
Sydney Laboratory - NATA # 1261 Site # 18217						X				
Mayfield West Laboratory - NATA # 1261 Site # 25079							X		X	X
External Laboratory										
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID					
1	Point 1 Outflow	Sep 16, 2025		Water	N25-Se0047054	X	X	X	X	X
2	Point 2 Upstream	Sep 16, 2025		Water	N25-Se0047055	X	X	X	X	X
Test Counts						2	2	2	2	2

Internal Quality Control Review and Glossary

General

1. Laboratory QC results for Method Blanks, Duplicates, Matrix Spikes, and Laboratory Control Samples follow guidelines delineated in the National Environment Protection (Assessment of Site Contamination) Measure 1999, as amended May 2013. They are included in this QC report where applicable. Additional QC data may be available on request.
2. Unless otherwise stated, all soil/sediment/solid results are reported on a dry weight basis.
3. Unless otherwise stated, all biota/food results are reported on a wet weight basis on the edible portion.
4. For CEC results where the sample's origin is unknown or environmentally contaminated, the results should be used advisedly.
5. Actual LORs are matrix dependent. Quoted LORs may be raised where sample extracts are diluted due to interferences.
6. Results are uncorrected for matrix spikes or surrogate recoveries except for PFAS compounds where annotated.
7. SVOC analysis on waters is performed on homogenised, unfiltered samples unless noted otherwise.
8. Samples were analysed on an 'as received' basis.
9. Information identified in this report with **blue** colour indicates data provided by customers that may have an impact on the results.
10. This report replaces any interim results previously issued.

Holding Times

Please refer to the 'Sample Preservation and Container Guide' for holding times (QS3001).

For samples received on the last day of holding time, notification of testing requirements should have been received at least 6 hours before sample receipt deadlines as stated on the SRA.

If the Laboratory did not receive the information in the required timeframe, and despite any other integrity issues, suitably qualified results may still be reported.

Holding times apply from the sampling date; therefore, compliance with these may be outside the laboratory's control.

For VOCs containing vinyl chloride, styrene and 2-chloroethyl vinyl ether, the holding time is seven days; however, for all other VOCs, such as BTEX or C6-10 TRH, the holding time is 14 days.

Units

mg/kg: milligrams per kilogram	mg/L: milligrams per litre	ppm: parts per million
µg/L: micrograms per litre	ppb: parts per billion	%: Percentage
org/100 mL: Organisms per 100 millilitres	NTU: Nephelometric Turbidity Units	MPN/100 mL: Most Probable Number of organisms per 100 millilitres
CFU: Colony Forming Unit	Colour: Pt-Co Units (CU)	

Terms

APHA	American Public Health Association
CEC	Cation Exchange Capacity
COC	Chain of Custody
CP	Client Parent - QC was performed on samples pertaining to this report
CRM	Certified Reference Material (ISO17034) - reported as percent recovery.
Dry	Where moisture has been determined on a solid sample, the result is expressed on a dry weight basis.
Duplicate	A second piece of analysis from the same sample and reported in the same units as the result to show comparison.
LOR	Limit of Reporting.
LCS	Laboratory Control Sample - reported as percent recovery.
Method Blank	In the case of solid samples, these are performed on laboratory-certified clean sands and in the case of water samples, these are performed on de-ionised water.
NCP	Non-Client Parent - QC performed on samples not pertaining to this report, QC represents the sequence or batch that client samples were analysed within.
RPD	Relative Percent Difference between two Duplicate pieces of analysis.
SPIKE	Addition of the analyte to the sample and reported as percentage recovery.
SRA	Sample Receipt Advice
Surr - Surrogate	The addition of a similar compound to the analyte target is reported as percentage recovery. See below for acceptance criteria.
TBTO	Tributyltin oxide (<i>bis</i> -tributyltin oxide) - individual tributyltin compounds cannot be identified separately in the environment; however, free tributyltin was measured, and its values were converted stoichiometrically into tributyltin oxide for comparison with regulatory limits.
TCLP	Toxicity Characteristic Leaching Procedure
TEQ	Toxic Equivalency Quotient or Total Equivalence
QSM	US Department of Defense Quality Systems Manual Version 6.0
US EPA	United States Environmental Protection Agency
WA DWER	Sum of PFBA, PFPeA, PFHxA, PFHpA, PFOA, PFBS, PFHxS, PFOS, 6:2 FTSA, 8:2 FTSA

QC - Acceptance Criteria

The acceptance criteria should only be used as a guide and may be different when site-specific Sampling Analysis and Quality Plan (SAQP) have been implemented.

RPD Duplicates: Global RPD Duplicates Acceptance Criteria is ≤30%; however, the following acceptance guidelines are equally applicable:

Results <10 times the LOR:	No Limit
Results between 10-20 times the LOR:	RPD must lie between 0-50%
Results >20 times the LOR:	RPD must lie between 0-30%

NOTE: pH duplicates are reported as a range, not as RPD

Surrogate Recoveries: Recoveries must lie between 20-130% for Speciated Phenols & 50-150% for PFAS. SVOCs recoveries 20 – 150%, VOC recoveries 50 – 150%

PFAS field samples containing surrogate recoveries above the QC limit designated in QSM 6.0, where no positive PFAS results have been reported or reviewed, and no data was affected.

QC Data General Comments

1. Where a result is reported as less than (<), higher than the nominated LOR, this is due to either matrix interference, extract dilution required due to interferences or contaminant levels within the sample, high moisture content or insufficient sample provided.
2. Duplicate data shown within this report that states the word "BATCH" is a Batch Duplicate from outside of your sample batch but within the laboratory sample batch at a 1:10 ratio. The Parent and Duplicate data shown are not data from your samples.
3. pH and Free Chlorine analysed in the laboratory - Analysis on this test must begin within 30 minutes of sampling. Therefore, laboratory analysis is unlikely to be completed within holding time. Analysis will begin as soon as possible after sample receipt.
4. Recovery Data (Spikes & Surrogates) - where chromatographic interference does not allow the determination of recovery, the term "INT" appears against that analyte.
5. For Matrix Spikes and LCS results, a dash "-" in the report means that the specific analyte was not added to the QC sample.
6. Duplicate RPDs are calculated from raw analytical data; thus, it is possible to have two sets of data.

Quality Control Results

Test			Units	Result 1			Acceptance Limits	Pass Limits	Qualifying Code
Method Blank									
Ammonia (as N)			mg/L	< 0.01			0.01	Pass	
Oil & Grease (HEM)			mg/L	< 10			10	Pass	
LCS - % Recovery									
Ammonia (as N)			%	88			70-130	Pass	
Conductivity (at 25 °C)			%	100			70-130	Pass	
Oil & Grease (HEM)			%	94			70-130	Pass	
Total Suspended Solids Dried at 103°C to 105°C			%	103			70-130	Pass	
Test	Lab Sample ID	QA Source	Units	Result 1			Acceptance Limits	Pass Limits	Qualifying Code
Spike - % Recovery									
				Result 1					
Ammonia (as N)	S25-Se0048520	NCP	%	84			70-130	Pass	
Test	Lab Sample ID	QA Source	Units	Result 1			Acceptance Limits	Pass Limits	Qualifying Code
Duplicate									
				Result 1	Result 2	RPD			
Ammonia (as N)	S25-Se0048519	NCP	mg/L	< 0.01	< 0.01	<1	30%	Pass	
Oil & Grease (HEM)	M25-Se0057734	NCP	mg/L	12	10	18	30%	Pass	

Comments

Sample Integrity

Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	No
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Authorised by:

Nileshni Goundar	Analytical Services Manager
Kirra Bailey	Senior Analyst-Inorganic
Luke Holt	Senior Analyst-Inorganic
Ryan Phillips	Senior Analyst-Inorganic



Glenn Jackson
Managing Director

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please [click here](#).

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.

Eurofins Environment Testing Australia Pty Ltd

ABN: 50 005 085 521

Melbourne
6 Monterey Road
Dandenong South
VIC 3175
+61 3 8564 5000
NATA# 1261
Site# 1254

Geelong
19/8 Lewalan Street
Grovedale
VIC 3216
+61 3 8564 5000
NATA# 1261
Site# 25403

Sydney
179 Magowar Road
Girraween
NSW 2145
+61 2 9900 8400
NATA# 1261
Site# 18217

Canberra
Unit 1,2 Dacre Street
Mitchell
ACT 2911
+61 2 6113 8091
NATA# 1261
Site# 25466

Brisbane
1/21 Smallwood Place
Murarrie
QLD 4172
+61 7 3902 4600
NATA# 1261
Site# 20794 & 2780

Newcastle
1/2 Frost Drive
Mayfield West
NSW 2304
+61 2 4968 8448
NATA# 1261
Site# 25079

Eurofins ARL Pty Ltd

ABN: 91 05 0159 898

Perth
46-48 Banksia Road
Welshpool
WA 6106
+61 8 6253 4444
NATA# 2377
Site# 2370 & 2554

Sample Receipt Advice

Company name: Australian Native Landscapes NSW
Contact name: Glenn Graves
Project name: Not provided
Project ID: WESTON ANL
Turnaround time: 5 Day
Date/Time received: Sep 16, 2025 10:25 AM
Eurofins reference: 1268587

Sample Information

- ✓ A detailed list of analytes logged into our LIMS, is included in the attached summary table.
- ✓ All samples have been received as described on the above COC.
- ✓ COC has been completed correctly.
- ✗ Attempt to chill was evident.
- ✓ Appropriately preserved sample containers have been used.
- ✓ All samples were received in good condition.
- ✓ Samples have been provided with adequate time to commence analysis in accordance with the relevant holding times.
- ✓ Appropriate sample containers have been used.
- ✓ Sample containers for volatile analysis received with zero headspace.
- ✗ Split sample sent to requested external lab.
- ✗ Some samples have been subcontracted.
- N/A Custody Seals intact (if used).

Notes

Contact

If you have any questions with respect to these samples, please contact your Analytical Services Manager:

Andrew Black on phone : (+61) 2 9900 8490 or by email: Andrew.Black@eurofinsanz.com

Results will be delivered electronically via email to Glenn Graves - glenn@anlscape.com.au.

ANL NSW (WESTON ANL)	Point 1 Outflow N25-Se0047054	Point 2 Upstream N25-Se0047055
Ammonia (as N)	0.02	0.02
Conductivity (at 25 °C)	860	860
Oil & Grease (HEM)	< 10	< 10
pH (at 25 °C)	7.1	7.7
Total Suspended Solids Dried at 103°C to 105°C	< 5	11



Melbourne Laboratory
6 Monterey Road Dandenong South VIC 3175
03 8564 5000 EnviroSampleVic@eurofins.com

Submission of samples to the laboratory will be deemed as acceptance of Eurofins | Environment Testing Standard Terms and Conditions unless agreed otherwise. A copy is available on request.